

A. ART 385 SHOULD BE FLOWN LOCALLY TO CONFIRM OPERATIONAL 25X1A READINESS AFTER MAINTENANCE REQUIRED AS INDICATED IN REF C.

I AGREE.

25X1A B. SYSTEM STILL INOPERATIVE. ETIC UNKNOWN AT THIS TIME. REF B.

TOPSECRET

TOR: 170534Z AUG 66

TOPSECRET

CROUP A
CROSS CONTRACTOR
CROSS CONTRACTO

REPRODUCTION PROPERTY FOR FOLKS 1200312/23 CIA RUPS BB00320R000100030043-2